

# FCI Partners with BA for RJ200 Air Flow Upgrade Campaign

Part Number: 016498-03  
ATA Number: 016498-21-01  
Location: Cockpit Display  
Service Bulletin: 08EN000548

**Nuisance "Display Cooling"  
alarms will be eliminated**



Part Number: 009579-08  
ATA Number: 009579-21-02  
Location: Airinc Supply  
Service Bulletin: 08EN000554

**Nuisance "Display Cooling"  
alarms will be eliminated**

Part Number: 009579-09  
ATA Number: 009579-21-03  
Location: In A/C Display Exhaust  
Service Bulletin: 08EN000555

**Nuisance "Display Cooling"  
alarms will be eliminated**



Web: [www.fluidcomponents.com](http://www.fluidcomponents.com) Headquarters: 1755 La Costa Meadows Drive, San Marcos, CA 92089; 760-744-6950;

800-863-6702 European Office: Porsephorstraat 3-01, 5047 TT Tilburg, The Netherlands; 31-13-515880